

# Certificate Surveillance audit

The quality system of the company



Manufacturer: **RECKMANN GMBH**

Address: **Werkzeugstr. 19 - 23, 58093 Hagen, Germany**

Site(s) of manufacture: **Werkzeugstr. 19 - 23, 58093 Hagen, Germany**

has been assessed through the audit of 2022-03-10 until 2022-03-11 in accordance with Article 13 in connection with Annexes IV and VII of Directive 2014/34/EU of the European Parliament and the Council for equipment and protective systems intended for use in potentially explosive areas.

Herewith it is certified that the notification with identification no. BVS 20 ATEX ZQS/E156 remains valid.

The audit report ZQS/E156/22 of 2022-03-14 as well as the updated annex of all monitored products together with their respective type examination certificate numbers are part of this document.

According to Article 16 (3) of the Directive 2014/34/EU the CE marking shall be followed by the identification number 0158 of DEKRA Testing and Certification GmbH as notified body involved in the production control phase.

DEKRA Testing and Certification GmbH  
Bochum, 2022-03-14

Managing Director